

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #1. North elevation looking SW, shot 01-08-21.



Photo #2. North elevation looking SE, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #3. Main entrance, north elevation looking SW, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #4. East elevation (north side) looking SW, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #5. East elevation (south side) looking SW, shot 05-15-22.



Photo #6. South elevation (left) & east elevation (right) looking NW, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #7. South elevation looking NW, shot 05-15-22.



Photo #8. Addition, west elevation (left) & south elevation (right) looking NE, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #9. West (left) and south (right) elevations of Addition looking SE, shot 05-15-22.



Photo #10. Main block (left) & Addition (left) looking SE, shot 05-15-22.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #11. Exterior brick (sample) looking W, shot 01-08-19.



Photo #12. Lobby w/entrance vestibule (center left) looking NW, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #13. Main office w/entrance vestibule (center) looking NE, shot 01-08-19.



Photo #14. Main lobby looking NW, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #15. Showroom looking NW, shot 01-08-19.



Photo #16. Main floor looking SSE, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #17. Main floor looking SE, shot 01-08-19.



Photo #18. Main floor looking NE, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #19. Main floor looking NW, shot 01-08-19.



Photo #20. Typical commercial style window looking E, shot 04-14-20.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #21. Roof trusses exposed looking N, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #22. Skylight exposed looking N, shot 01-08-19.



Photo #23. Bowstring trusses exposed looking N, shot 01-08-19.

International Harvester Truck Sales and Service Center, Davenport, Iowa



Photo #24. Addition looking NE, shot 01-08-19.



Photo #25. Addition looking SW, shot 01-08-19.